

Deactivated PMEP Regression




FIG - 5

Deactivated FMEP Regression




FIG - 6

Spark Retard Torque Reduction Regression




FIG - 7







FIG - 8





	•	COLUMN 0			COLUMN 3		
DECREASING TORQUE	V2	1	1	1	1	ROW 3	
	12-STROKE	1	1	1	1	FIG - 11	
	V4	1	1	1	1	<u> </u>	
	V8	1	1	1	1	ROW 0	
	·	DIDE	DIAE DECREASIA	AIDE NG TORQUE	AIAE		

		COLUMN 0			COLUMN 3		
3 TORQUE	<i>V2</i>	0	0	. 0	0	ROW 3	
	12-STROKE	0	0	0	0		FIG - 12
DECREASING TORQUE	V4	1	1	0	0	•	<u> 110 - 12</u>
	V8	1	1	1	1	ROW 0	
		DIDE	DIAE DECREASIN	AIDE IG TORQUE	AIAE		







FIG - 14






FIG - 16








FIG - 17









Exhaust Side

FIG - 21A







FIG-22



Exhaust Side

FIG - 23








FIG - 26




FIG-27





FIG - 28










FIG - 30


Speed and Torque Dependant Mode Changes



































FIG - 40









FIG - 41


















































FIG - 54




FIG - 55